## NRO REVIEW COMPLETED

Copy 6 of 6

2 6 AUG 1963

MEMORANDUM FOR: AFIGO-S

Headquarters USAF

ATTENTION

: Colonel Leo P. Geary

SUBJECT

: Rotor Assembly, P/R BB-4-6115-06025

- 1. As requested in your 1st Indorsement, dated 13 August 1963, the following details pertaining to the damage to subject Rotor Assembly are submitted.
  - a. On 25 March 1963 a Rotor Assembly for a turbocharger, Part No. 876N-6115-00-0215, Serial No. U-9118-5, Model L-604, Size 1L3-PBT-7313, Style B", was ordered on Voucher No. 63-26052, Request No. 5654, for 1250 KW Generator No. 58038. This Rotor Assembly was received and installed on 1250 KW Generator No. 58038.
  - The Rotor Assembly removed from the Generator was turned in on 10 June 1963 on Voucher No. 63-37571. dated 10 June 1963, for overhaul and re-This Rotor Assembly was received turn as a used assembly with Generator No. 58038 from hinot, North Dakota, and had 6,000 running hours before it was removed. Previous running time at Minot is unknown. The grind or balance marks on the blades were made by the Elliott Company in order to balance the assembly.
- statement in his letter of 30 July 2. 1963 is misleading, as we are dealing with two separate Rotor Assemblies; and the warranty on the one sent in for rebuilding has expired. The Rotor Assembly purchased in May 1963

25X1

25X1

Approved For Release 2002/09/03 : CIA-RDP63-00313A000500130057-1

NRO 25X1

25X1

25X1

## Approved For Release 2002/09/03: CIA-RDP63-00313A000500130057-1 SECRET

	Page Two	25X1
(paragraph 1.a.) is presently inst Generator No. 58038 and was not re The Rotor Assembly discussed in pa the one returned.	sturned for overhaul. aragraph l.b. above was	
FOR THE DEPUTY DIRE	ector (science and technology)	25X1
MD/OSA (23 Aug 63) Distribution: Copy 1 - AFIGO-S	Po JACK C. LEDFORD Colonel USAF	

25X1

(23 Aug MD/OSA Copy 1 - AFIG Distribution: 2 - AD/OSA

3 - D/FA/OSA4 - MD/OSA 5 - Chrono 6 - RB/OSA